


Cool Grain to Prevent Storage Problems



* Prevent crusting due to moisture migration by cooling grain to within 15°F of average outdoor temperatures.

* Cooling grain by 10°F doubles its allowable storage time

Kenneth J. Hellevang
NDSU Extension Service